

Seal Coat 2023 CSJ 0011-09-075

1. Items 666 6322, 666 6323, 666 6326, and 666 6327 call out for Retro Requirements. The 2014 Specification Book only has a minimum retro value for TY I markings and no retro value for TY II markings. Will there be a minimum value that must be met or will the retro requirements be waived for these 4 Items?

[Per spec, TY II pavement markings do not require retro reflectivity testing.](#)

2. Addendum has been issued for adding SP 006-001.

3. Addendum 2 has been issued.