

RMC 6354-61-001
 Roadway:Fm1603
 Various Roadways in Navarro County Maintenance Section
 Letting Date: April 2020

30-Mar-20

No.	Questions	Answers
1	How will the presence of exiting concrete paving be addressed on FM 3383?	If you encounter concrete within the specified depth do not proceed any deeper place 2% cement stabilized flexible Base followed by specified surface treatment.
2	Item 351. Is it the intent to stabilize the existing material in place at all locations?	No, Remove existing material and replace with new cement stabilized Flex Base followed by the 2 course surface treatment.
3	Item 351 there are , what could appear to be, conflicting notes present in the General Notes for this item. The third paragraph states “ Do not expose any location that cannot receive, at a minimum, a single surface treatment or the final pavement surface in any one day.” paragraph 7 states “ only open and process areas that can be completed, and the first course treatment applied within the same work week..” Which note will be held? Paragraph 7 seems to be the logical method. Paragraph 3, if used as stated, would greatly hamper production on the project. Please clarify	The first note is regarding Flexible Pavement A (Asphalt) repair and the second note is for Flexible Structure E (Base repair).
4	Reference General Notes, Item 351- Flex Pavement Struct Repair. The fifth sentence calls out Flex Base TY”D” to be placed in the cut outs. What grade of base is required for repairs?	Grade 4
5		
6		

7		
8		
9		
10		