



2501 SOUTHWEST LOOP 820 • FORT WORTH, TEXAS 76133 • (817) 370-6500

0902-00-201, VA, Tarrant County, ETC

Contractor Questions and TxDOT Responses

(The responses are in red)

1. Both IH 20 @ Cooper St. & NB IH 820 @ Ramey St. have 4 ea. drill shafts that are shown to be removed. Thus, bring the overall total for bid item 496-6035 to 16 ea. instead of 8.

Bid as shown in plans estimate (pg. 5).

2. The existing structure at EB IH 30 @ Spur 580 seems that it's going to be removed as well, bringing the total for bid item 650-6204 to 4 ea. instead of 3.

The overhead truss and support towers have already been removed at this location. Bid as shown in plans estimate (pg. 5).

3. Will it be the contractor's responsibility to remove the 3 signs that are on each sign column and reinstall them on the new sign structure at location EB IH 30 @ Spur 580?

There are no signs at this location. See question 2. New signs are to be installed on the new structure. See sheet 69 in plans.