

PRE-BID QUESTION AND ANSWER #1

RMC 6408-53-001

DATE	QUESTION/REQUEST	RESPONSE	RESPONSE DATE
1/29/2023	Should item 462-6010 be 432-6010?	Item 462-6010 was intended to be item 432-6010 (RIPRAP (CONC)(CL B)(5 IN) by the CY. Any overrun or underruns in the plans will be addressed as outlined in the Spec Book under Item 4, "Scope of Work."	1/30/2023
1/29/2023	At the SH 35 site there is riprap under the 4 ends of the bridges, is the intent to place flowable fill under all 4 locations?	Use sheet 15 for details of proposed work at SH 35 at both the North and South abutments	1/30/2023
1/29/2023	How will we be allowed to access the Fm 521 West end?	The Contractor can access the bridge within TxDOT right of way	1/30/2023