

RMC 6341-10-001  
Answers to Contractor Questions  
(TxDOT answers in RED)

1. In regards to bid item 0545 6001, per general note item 774 details are to be furnished on the method proposed to retrofit new systems at existing locations. Plans do not include pertinent information such as Test level, hazard description (detail), width, and direction of traffic. Can you please advise on this information since it is excluded from the plans?
  - a. This contract is for callout repair, therefore this information cannot be provided until needed.
  
2. The standard included in the plans has 3 different test levels; do you have any idea what test level would be required?
  - a. This contract is for callout repair. Therefore this information can only be determined based on the specific needs of the individual repair request.