

PROSPECTIVE BIDDER'S INQUIRIES

RMC: 6368-36-001 (San Jacinto County) Tree Trim & Brush Removal

Bid Opening Date: 09/30/2020

No.	QUESTION	TxDOT MNT OFFICE RECEIVED QUESTION FROM BIDDER	RESPONSE
		DATE	
1	How many miles of "Tree Trimming/Brush Removal" are in the contract? A: As shown on sheet 3 and 4 of the plans, 35 Miles of "Tree Trimming/Brush Removal" are included in this contract.	09/10/2020	As shown on sheet 3 and 4 of the plans, 35 Miles of "Tree Trimming/Brush Removal" are included in this contract.
2	Do you have 1 Or 2 roadways that you will be working on for the tree trimming/brush removal?	09/10/2020	The "Various Locations" shown in the plans are to be used at the Maintenance Section Supervisor's discretion. The areas that need trimming will be determined and then discussed with the contractor at that time.
3	Will contactors be allowed to spread chips on ROW into this layer?	9/11/2020	Yes. The only exception is near culvert locations. The chips will have to be moved away from these locations. Coordination with the maintenance section is required for these locations.
4	Removing the brush is at fence line.	9/11/2020	Tree Trimming and brush removal is at the ROW line which typically is at the fence line. Coordination with the maintenance supervisor prior to work is required.
5	Please provide location for trimming and brush removal.	9/11/2020	The "Various Locations" shown in the plans are to be used at the Maintenance Section Supervisor's discretion. The areas that need trimming will be determined and then discussed with the contractor at that time.
6	Do we have to grind the stump.	9/11/2020	Yes

7	Location for channel.	9/11/2020	The "Various Locations" shown in the plans are to be used at the Maintenance Section Supervisor's discretion. The areas that need trimming will be determined and then discussed with the contractor at that time.
8	Will contactors be allowed to spread chips on ROW into this layer?	9/11/2020	Yes. The only exception is near culvert locations. The chips will have to be moved away from these locations. Coordination with the maintenance section is required for these locations.