

Tex-737-I, Sampling Flexible Delineator and Object Marker Posts

Contents:

Section 1 — Overview.....	2
Section 2 — Sampling Information.....	3
Section 3 — Procedures.....	4
Section 4 — Tagging/Labeling, Documenting, and Shipping.....	5

Section 1

Overview

Effective Dates: August 1999–September 2007.

This method outlines the procedure for taking samples of flexible delineator and object marker posts.

Units of Measurement

The values given in parentheses (if provided) are not standard and may not be exact mathematical conversions. Use each system of units separately. Combining values from the two systems may result in nonconformance with the standard.

Section 2

Sampling Information

An authorized representative of TxDOT shall select samples.

Samples may be taken at the jobsite or at an approved TxDOT stocking location prior to shipment to the jobsite.

Section 3

Procedures

A sample shall consist of a minimum of three flexible posts selected from each lot or shipment of a particular type or size.

Select samples, at random, that are representative of materials being supplied.

NOTE: Samples will not be required when project quantities of a particular type or size of flexible post consist of 25 units or less. These posts will be visually inspected by the engineer, and a certificate of compliance will be furnished by the manufacturer.

Section 4

Tagging/Labeling, Documenting, and Shipping

Follow the 'General Requirements' as detailed in "Tagging/Labeling, Documenting, and Shipping General Requirements." In addition:

- ◆ tag or mark each sample, in a non-destructive manner, with the name of the flexible post, manufacturer's name, and quantity represented by the sample
- ◆ include information pertinent to each sample on [Form 202](#)
- ◆ wrap bundle to prevent damage in transit.